



# fractus

Optimised Antennas  
for Wireless Devices

## RoHS Certificate of Compliance

### SUPPLIER INFORMATION

Supplier Name: **Fractus, S.A.**  
 Address: **Avd. Alcalde Barnils, 64-68**  
 City: **Sant Cugat del Vallès**  
 Phone: **+34 935 442 690**  
 Fax: **+34 935 442 691**  
 Zip: **08174**  
 State: **SPAIN**  
[www.fractus.com](http://www.fractus.com)

### CONTACT PERSON

Supplier contact name: **Elena Gracia**  
 Title: **Supply Chain Manager**  
 Email address: [elena.gracia@fractus.com](mailto:elena.gracia@fractus.com)  
 Phone: **+34 935 442 690**

Product Part Number **FR05-S1-NO-1-004**  
 Product Name **Compact Dual Band Reach Xtend™ Chip antenna**

### DECLARATION STATEMENT OF MATERIAL CONTENTS

Review Date **24/11/2006**



Banned Substances	Units	Method Detection Limit (ppm)	Results
(Pb) Lead and Lead Compounds	mg/Kg	5	Material Not Detected
(Pb) Soldering with Lead	mg/Kg	5	Material Not Detected
(Cd) Cadmium and Cadmium Compounds	mg/Kg	0.5	Material Not Detected
(Hg) Mercury and Mercury Compounds	mg/Kg	2	Material Not Detected
(Cr <sup>+6</sup> ) Hexavalent Chromium and Hexavalent Chromium Compounds	mg/Kg	1	Material Not Detected
Polybrominated Biphenyls(PBBs)/ Polybrominated Biphenyls Ethers(PBDEs)	mg/Kg	5	Material Not Detected
Chlorofluorocarbons(CFCs)/ Hydrochlorofluorocarbons(HCFC)	mg/Kg	0	Material Not Detected
Polychlorinated Biphenyls(PCBs)	mg/Kg	0	Material Not Detected
Asbestos	mg/Kg	0	Material Not Detected
Radioactive Materials	mg/Kg	0	Material Not Detected